

## 2023 Repair packages

Applicable from 1 July 2023

**MANDATORY !** This document must be filled and attached to the equipment sent for repair.

Ref.	Description	Price 2023 € (excl. VAT)	DG
760006	REPAIR CROSSBOW 2501/2500/2503	88,70	V7
760012	REPAIR RAM 240201	384,10	V7
760013	REPAIR RAM 240202	384,10	V7
760014	REPAIR RAM 240203	474,40	V7
760015	REPAIR RAM 240801	384,10	V7
760016	REPAIR RAM 240802	384,10	V7
760017	REPAIR RAM 240803	536,60	V7
760018	REPAIR VAL35 291000	218,60	V7
760019	REPAIR VAL35E 291001	274,00	V7
760020	REPAIR VAL80 291200	330,10	V7
760021	REPAIR VAL80E 291201	469,20	V7
760022	REPAIR VAL90 292030	549,10	V7
760023	REPAIR SIBERIA® 221070	358,10	V7
760024	REPAIR BENDER 2518	370,60	V7
760026	REPAIR I10	274,00	V7
760031	REPAIR GAS CONTROLLER 262080	80,40	V7
760033	REPAIR TEST PUMP 262035	143,00	V7
760034	REPAIR PHENIX III 137563	274,00	V7
760037	REPAIR VIRAFAL®	695,50	V7
760038	REPAIR MINI-CRIMPER 253350	87,50	V7
760039*	CHECK VIPER® M21+/ML21+/M2X/L2X/P25+	63,50	V7
760040	REPAIR VIPER® M21+/ML21+/M2X/L2X	349,80	V7
760041	REPAIR VIPER® P25+	430,80	V7
760045	REPAIR VIPER® i26+	271,30	V7

\* The check (ref. 760039) will be free if a repair on VIPER M21+/ML21+/M2X/L2X/P25+ (ref.760040 and ref.760041) is necessary.

**Your SAS contact : [sav@virax.com](mailto:sav@virax.com)**

NB : You can download this document on [www.virax.com](http://www.virax.com) section « After Sales Service »