

2021 Repair packages

Applicable to 1st July 2021

MANDATORY ! This document must be filled and attached to the equipment sent for repair.

Ref.	Description	Price 2021 € (excl. VAT)	DG
760006	REPAIR PACKAGE CROSSBOW 2501	76,10	V7
760012	REPAIR PACKAGE RAM 240201	329,60	V7
760013	REPAIR PACKAGE RAM 240202	329,60	V7
760014	REPAIR PACKAGE RAM 240203	406,90	V7
760015	REPAIR PACKAGE RAM 240801	329,60	V7
760016	REPAIR PACKAGE RAM 240802	329,60	V7
760017	REPAIR PACKAGE RAM 240803	459,50	V7
760018	REPAIR PACKAGE VAL35 291000	187,40	V7
760019	REPAIR PACKAGE VAL35E 291001	234,90	V7
760020	REPAIR PACKAGE VAL80 291200	283,30	V7
760021	REPAIR PACKAGE VAL80E 291201	401,70	V7
760022	REPAIR PACKAGE VAL90 292030	470,80	V7
760023	REPAIR PACKAGE SIBERIA 221070	307,00	V7
760024	REPAIR PACKAGE BENDER 2518	317,30	V7
760026	RECALIBRATION/REPAIR PACKAGE I10/I11/P10	234,90	V7
760031	GAS CONTROLLER REPAIR PACKAGE 262080	69,00	V7
760033	REPAIR PACKAGE 262035 TEST PUMP	122,60	V7
760034	REPAIR PACKAGE 137563 PHENIX III	234,90	V7
760036	RECALIBRATION/REPAIR PACKAGE VIPER P22	378,10	V7
760037	REPAIR PACKAGE VIRAFAL	596,40	V7
760038	REPAIR PACKAGE 253350 MINI-CRIMPER	75,10	V7
760039*	CHECK/CALIBRATION PACKAGE VIPER M21+	54,50	V7
760040	REPAIR PACKAGE VIPER M21+	299,70	V7
760041	RECALIBRATION PACKAGE VIPER P25+	368,80	V7
760045	RECALIBRATION PACKAGE VIPER i25+	232,50	V7

* The check/calibration package VIPER M21+ (ref. 760039) will be free if a repair on VIPER M21+ (ref.760040) is necessary.

Please send your equipment to **EPERNAY** at the following address :

SAV Virax: 39, quai de Marne - 51206 EPERNAY Cedex
Fax : 03 26 59 56 50

Your order n° :

+ Shipping fees (28€)

Date :

NB : You can download this document on www.virax.com section «Documentations»