

2022 Repair packages

Applicable to 1st January 2022

MANDATORY ! This document must be filled and attached to the equipment sent for repair.

Ref.	Description	Price 2022 € (excl. VAT)	DG
760005	REPAIR PACKAGE RECIPROCATING SAW 045000	239,50	V7
760006	REPAIR PACKAGE CROSSBOW 2501	77,60	V7
760012	REPAIR PACKAGE RAM 240201	336,10	V7
760013	REPAIR PACKAGE RAM 240202	336,10	V7
760014	REPAIR PACKAGE RAM 240203	415,00	V7
760015	REPAIR PACKAGE RAM 240801	336,10	V7
760016	REPAIR PACKAGE RAM 240802	336,10	V7
760017	REPAIR PACKAGE RAM 240803	468,60	V7
760018	REPAIR PACKAGE VAL35 291000	191,10	V7
760019	REPAIR PACKAGE VAL35E 291001	239,50	V7
760020	REPAIR PACKAGE VAL80 291200	288,90	V7
760021	REPAIR PACKAGE VAL80E 291201	409,70	V7
760022	REPAIR PACKAGE VAL90 292030	480,20	V7
760023	REPAIR PACKAGE SIBERIA 221070	313,10	V7
760024	REPAIR PACKAGE BENDER 2518	323,60	V7
760026	RECALIBRATION/REPAIR PACKAGE I10/I11/P10	239,50	V7
760031	GAS CONTROLLER REPAIR PACKAGE 262080	70,30	V7
760033	REPAIR PACKAGE 262035 TEST PUMP	125,00	V7
760034	REPAIR PACKAGE 137563 PHENIX III	239,50	V7
760036	RECALIBRATION/REPAIR PACKAGE VIPER P22	385,60	V7
760037	REPAIR PACKAGE VIRAFAL	608,30	V7
760038	REPAIR PACKAGE 253350 MINI-CRIMPER	76,60	V7
760039*	CHECK/CALIBRATION PACKAGE VIPER M21+	55,50	V7
760040	REPAIR PACKAGE VIPER M21+	305,60	V7
760041	RECALIBRATION PACKAGE VIPER P25+	376,10	V7
760045	RECALIBRATION PACKAGE VIPER i25+	237,10	V7

* The check/calibration package VIPER M21+ (ref. 760039) will be free if a repair on VIPER M21+ (ref.760040) is necessary.

Please send your equipment to **EPERNAY** at the following address :

SAV Virax: 39, quai de Marne - 51206 EPERNAY Cedex
Fax : 03 26 59 56 50

Your order n° :

+ Shipping fees (28€)

Date :